





**ANGELL PLUMBING, INC.**

831 Prairie Trail • Austin, TX 78758  
(512) 837-0275 • Fax (512) 837-5715

# Invoice

**DATE****INVOICE #**

6/23/00

60278

**BILL TO:**

Bealls  
P.O. Box 35668  
Houston, TX 77235

**P.O. NUMBER****TERMS****PROJECT**

Net 10

**QUANTITY****DESCRIPTION****RATE****AMOUNT**

Job: FM 1825 @ Wells Branch  
Pflugerville, TX  
Store #0133

Installed new power flush tank on toilet per proposal

Per proposal

325.00

325.00

PAYMENT IS DUE WITHIN 10 DAYS FROM THE DATE OF  
THIS INVOICE. PAST DUE BALANCES WILL ACCRUE  
INTEREST @ ALLOWABLE RATE OF LAW. THIS FIRM  
OPERATES UNDER THE LICENSURE OF THE TX STATE BD.  
OF PLUMBING EXAMINERS 929 E. 41st St. - P.O. Box 4200  
AUSTIN, TX 78765 512-458-2145 Lic. #ML11414

Thank you for your business.

**TOTAL**

\$325.00



**ANGELL PLUMBING, INC.**

831 Prairie Trail • Austin, TX 78758  
(512) 837-0275 • Fax (512) 837-5715

# Invoice

**DATE****INVOICE #**

6/12/00

60260

**BILL TO:**

Bealls  
P.O. Box 35668  
Houston, TX 77235

**P.O. NUMBER****TERMS****PROJECT**

Net 10

**QUANTITY****DESCRIPTION****RATE****AMOUNT**

Job: Bealls Store #0133

FM 1825 @ Wells Branch, Pflugerville, TX

Ladies toilet not flushing. Adjusted flush mechanism.  
Took tank apart but still could not get it to work. New  
tank is needed. (See attached proposal)

1.5

Labor 6/9/00

92.50

138.75T

Sales Tax

8.25%

11.45

PAYMENT IS DUE WITHIN 10 DAYS FROM THE DATE OF  
THIS INVOICE. PAST DUE BALANCES WILL ACCRUE  
INTEREST @ ALLOWABLE RATE OF LAW. THIS FIRM  
OPERATES UNDER THE LICENSURE OF THE TX STATE BD.  
OF PLUMBING EXAMINERS 929 E. 41st St. - P.O. Box 4200  
AUSTIN, TX 78765 512-458-2145 Lic. #ML11414

Thank you for your business.

**TOTAL**

\$150.20

1-713-218-



**ANGELL PLUMBING, INC.**831 Prairie Trail • Austin, TX 78758  
(512) 837-0275 • Fax (512) 837-5715

# Invoice

DATE

INVOICE #

4/24/00

40208

**BILL TO:**Bealls  
13802 Research  
Austin, TX 78750*1-713  
218-4470  
6454*

P.O. NUMBER

TERMS

PROJECT

Net 10

QUANTITY

DESCRIPTION

RATE

AMOUNT

Attn: Rhonda

Both drinking fountains not working properly.

Troubleshoot both drinking fountains. Have to order parts. Took parts from one to make 1 good one.

Installed new button &amp; bubbler on drinking fountain. Still could not get fountain to work. Need new drinking fountain.

1	Labor	87.50	87.50T
1	Labor	74.50	74.50T
	Materials	63.00	63.00T
	Sales Tax	8.25%	18.56

PAYMENT IS DUE WITHIN 10 DAYS FROM THE DATE OF THIS INVOICE. PAST DUE BALANCES WILL ACCRUE INTEREST @ ALLOWABLE RATE OF LAW. THIS FIRM OPERATES UNDER THE LICENSURE OF THE TX STATE BD. OF PLUMBING EXAMINERS 929 E. 41st St. - P.O. Box 4200 AUSTIN, TX 78765 512-458-2145 Lic. #ML11414

Thank you for your business.

**TOTAL****\$243.56**